

---

4 ALBERT EMBANKMENT  
LONDON SE1 7SR  
Telephone: +44 (0)20 7735 7611 Fax: +44 (0)20 7587 3210

MSC.1/Circ.1428  
28 May 2012

## **PILOT TRANSFER ARRANGEMENTS**

### **Required boarding arrangements for pilots**

1 The Maritime Safety Committee, at its eighty-eighth session (24 November to 3 December 2010), approved amendments to SOLAS regulation V/23 which, inter alia, include amendments to the Required Boarding Arrangements for Pilots (resolution MSC.308(88)). In addition, the twenty-seventh regular session of the Assembly, in December 2011, adopted resolution A.1045(27) on *Pilot transfer arrangements*.

2 These changes required amendments to the poster previously circulated under cover of MSC/Circ.568/Rev.1. The attached revised poster incorporates the most significant changes adopted by MSC 88.

3 The Maritime Safety Committee, at its ninetieth session (16 to 25 May 2012), concurred with the recommendation of the fifty-seventh session of the NAV Sub-Committee regarding Required boarding arrangements for pilots (6 to 10 June 2011) and approved a revision of the poster.

4 Member Governments are requested to bring the revised poster to the attention of their pilots, seafarers, shipowners, ship operators and others concerned with pilot boarding arrangements.

\*\*\*

ANNEX

# REQUIRED BOARDING ARRANGEMENTS FOR PILOT

In accordance with SOLAS Regulation V/23 & IMO Resolution A.1045(27)

INTERNATIONAL MARITIME PILOTS' ASSOCIATION



H.Q.S. "Wellington" Temple Stairs, Victoria Embankment, London WC2R 2PN Tel: +44 (0)20 7240 3973 Fax: +44 (0)20 7210 3518 Email: office@impahq.org  
This document and all IMO Pilot-related documents are available for download at: <http://www.impahq.org>

