

---

4 ALBERT EMBANKMENT  
LONDON SE1 7SR  
Telephone: +44 (0)20 7735 7611 Fax: +44 (0)20 7587 3210

MSC.1/Circ.1433  
31 May 2012

**UNIFIED INTERPRETATIONS OF SOLAS REGULATION II-2/10.6.4 AND  
CHAPTER 9 OF THE FSS CODE**

1 The Maritime Safety Committee, at its ninetieth session (16 to 25 May 2012), having considered a proposal by the Sub-Committee on Fire Protection, at its fifty-fifth session, approved the following unified interpretations of SOLAS regulation II-2/10.6.4 and the FSS Code (chapter 9):

- .1 With regard to the footnote to SOLAS regulation II-2/10.6.4.1, referring to the recommendations by the International Organization for Standardization, it should be interpreted as follows:

"Refer to the recommendations by the International Organization for Standardization, in particular publication ISO 15371:2009, Ships and marine technology – Fire-extinguishing systems for protection of galley cooking equipment. For ships constructed before 1 July 2013, ISO 15371:2000, Fire-extinguishing systems for protection of galley deep-fat cooking equipment – fire tests, may be used."

- .2 In paragraphs 2.3.1.2, 2.3.1.3 and 2.3.1.5 of chapter 9 of the FSS Code, as amended by resolution MSC.311(88), the referenced standard IEC 60092-505:2001 should be interpreted as IEC 60092-504.

2 Member Governments are invited to use the above unified interpretations as guidance when applying relevant provisions of SOLAS chapter II-2 and the FSS Code and to bring them to the attention of all parties concerned.

---