

FERÐAFÓLKALOYVI
PASSENGER PERMIT

Ferðafólkabátur
(Passenger boat)

NJØRÐUR

Slag (Type)

Navn (Name)

OW2473	Vestmanna	9,2	170	1989
Kenningarstavir <i>Distinctive number or letters</i>	Heimstaður <i>Port of registry</i>	Bruttotonnasja <i>Gross tonnage</i>	kW <i>Output</i>	Byggiár <i>Year of build</i>

Farið er sýna sambært:
The vessel is surveyed according to: Fráboðan F

Sjovinnustýrið hefur framt sýn hin:
The Faroese Maritime Authority have completed a survey on the: 05.05.2026

Farið kann fara í vinnu í / *the vessel may be employed in*

Siglingarøki: Sambært trygdarvegleiðing fyri farið. Sum nevnt í §4 í kunngerð 104 frá 2019
Trading area: According the risk assessment for the vessel. As mentioned in §4 in executive order 104 from 2019
GMDSS-radioøki: A1
GMSSS-radio area: A1 area

Hægst loyvda ferðafólkatal / *Total number of passengers permitted*

Summar (Summer) 1. mai – 30. september	12
Vetur (Winter) 1. oktober – 30. apríl	12

Loyvið er galdandi til hin:
This Permit will remain in force until the: 05.10.2026

Sandavágur hin
on the 05.05.2026

Undirskrift
Signature



Jógvan Hentze
SJÓVINNUSTÝRIÐ
Faroese Maritime Authority

Jógvan Hentze

Hetta loyvið er galdandi, so leingi farið verður hildið í sjódyggum standi. At útgerðin, viðlíkahald og manning er samsvarandi galdandi reglum. At siglingin fer fram innanfyri karmarnar í trygdarvegleiðingini, so leiðis at ásetingarnar verða hildnar.

This permit will remain valid, provided that the vessel is kept in a seaworthy state. That the equipment, maintenance, and manning requirements comply with the applicable rules. That the sailing activity is within the framework of the safety instruction, to ensure the provisions are complied with.

Miðsýn skal haldast hin: +/- 3 mánaðir
An intermediate survey to be held on: 05.10.2026 (+/- 3 months)

Átekning viðvíkjandi miðsýn / *Endorsement concerning intermediate survey*

Stað hin Navn Undirskrift
Place on the Name Signature

Eitt avrit av hesum loyvinum skal vera sjónligt hjá ferðafólkunum umborð.
A copy of this permit must be visibly displayed for passengers on board.